

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S21	363	((detect\$3 determin\$4 verif\$3 sens\$4) near3 (insulation)) and ((dissipation))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 13:10
S22	81	((detect\$3 determin\$4 verif\$3 sens\$4) near3 (insulation)) and ((dissipation) near3 factor\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 15:32
S23	1	("3961246").URPN.	USPAT	OR	OFF	2005/11/02 15:23
S24	69	((detect\$3 determin\$4 verif\$3 sens\$4) near3 (insulation)) same ((dissipation))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 15:53
S25	2	"5270640".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 15:53
S26	34	("5270640").URPN.	USPAT	OR	OFF	2005/11/02 15:54
S27	5	S26 and (dissipation)	USPAT	OR	OFF	2005/11/02 15:56
S28	476	((determin\$3 calculat\$3 detect\$3 sens\$4) near3 (dissipation)) same (voltage and current)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 15:58
S29	62	S28 and ((phasor phase) near3 (voltage current))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 15:59
S30	2	10/814839	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 16:20

S31	65	((dissipation near3 factor) same ((phase phasor) near3 (current voltage))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 16:53
S32	59	S31 not S29	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 16:21
S33	5	((dissipation near3 factor) with ((phase phasor) near3 (current voltage))) and (machine motor stator rotor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 16:54